

CITY OF SIOUX CITY, IOWA

UTILITIES DIVISION – SEWER SERVICE REPORT

✓ MAIN BACKUP PRIVATE SERVICE BACKUP SEWER GAS

1. Complaint Address MH in Soccer Field at Laurel Ave & S Palmetto
(House or Building Address)
2. Did an SSO occur Yes (If yes complete an SSO Report)
3. Received – Date 2-22-19 Time 1:00 PM
4. Arrived at Place – Date 2-22-19 Time 1:15 P.M
5. Depth of Sewage in Basement NA
6. Caused by City Main Yes
7. Caused by Private Sewer Service No
8. Location of Plug (if main) 1st MH N of Laurel : S Palmetto
9. Cause of Plug Tree limbs
10. Apparent Damage: (Furnace) (Water Heater) (Washer) (Dryer) (Other)

Contents: _____

11. Was Basement Cleaned by City Crews? No
12. Were Occupants Satisfied? Yes
13. Additional Information Jetted line 200 N From 1st MH
S of ~~the~~ S Palmetto & Laurel Ave
Note: We Will Bleach area of
area of known discharge

14. Reported by Mike Haming Title Manual Worker
- Date 2-22-19

CITY OF SIOUX CITY
FIELD SERVICES-UTILITIES
1921 18TH ST, SIOUX CITY, IA 51105

SSO REPORT

X PUBLIC PRIVATE

LOCATION OF INCIDENT: Laurel Ave & S Palmetto

REPORTED BY: Alex Zimmerman DATE: 2-22-19 TIME: 3:45p

SENT TO (IDNR STAFF NAME): Tom Ross (EMAIL, PHONE, FAX)

SSO START DATE: 2-22-19 SSO START TIME: 1:15pm

SSO STOP DATE: 2-22-19 SSO STOP TIME: 2:00pm

ESTIMATED VOLUME (IN GALLONS): 50

CONTENTS OF SSO: sewage

REASON FOR SSO: sticks and branches thrown in manhole

DID THE SSO REACH THE STORM SYSTEM: NO

IF YES, LOCATION OF OUTLET (NAME OF WATERBODY): N/A

DISTANCE TRAVELED ON SURFACE: 15'

DISTANCE TRAVELED IN STORM SYSTEM TO OUTLET: NA

ACTION TAKEN TO STOP SSO: cleared blockage removed branches

PLANNED ACTION TO PREVENT FUTURE SSO (IF POSSIBLE): monitor manhole
possibly have weld job

SAMPLING REQUIRED: NO LOCATION OF SAMPLES: N/A

ADDITIONAL COMMENTS: Applied bleach solution to
area.